



National Inspection Services  
# : 179219 on 01/17/2020  
VIN: 1S12E9530DE526780 Unit: 13108

InPlaceAuction LLC. Ed Castagna  
68 S Service Rd Melville, NY 11747 USA  
(516) 297-7775

## 2013 STRICK DRY VAN TRAILER

DRY VAN TRAILER Specifications	
Axles	Tandem 20,000 Front / 20,000 Rear
Spread Axle	No
Suspension	Air Ride
Tire Size F	295/75R22.5
Tire Size R	295/75R22.5
Wheels	Steel
Rear Door	Swing
Interior Height	110"
Exterior	162"H 102"W 53'L
Exterior Color	WHITE

Drive Options

### Inspection Photos



### Notes / Description

HUB READING = 140857



National Inspection Services  
# : 179219 on 01/17/2020  
VIN: 1S12E9530DE526780 Unit: 13108

InPlaceAuction LLC. Ed Castagna  
68 S Service Rd Melville, NY 11747 USA  
(516) 297-7775

## 2013 STRICK DRY VAN TRAILER PHOTOS





National Inspection Services  
 # : 179219 on 01/17/2020  
 VIN: 1S12E9530DE526780 Unit: 13108

InPlaceAuction LLC. Ed Castagna  
 68 S Service Rd Melville, NY 11747 USA  
 (516) 297-7775

## 2013 STRICK DRY VAN TRAILER

Brakes	
16	16
15	15
Additional Brake Detail	

Tires			
Front 295/75R22.5	/ 32	/ 32	Rear 295/75R22.5
17 / 32 Steel	14 / 32 Steel	Michelin 11 / 32 Steel	Goodyear 5 / 32 Steel
11 / 32 Steel	Goodyear 9 / 32 Steel	13 / 32 Steel	12 / 32 Steel
Additional Tire Detail			
TIRES=INNING & IRONMAN			

General Observations						
Oil Milky?	Oil Leaks?	NA	Water Leaks?	NA	Oil in Coolant?	NA
Clutch Play?	NA	Starts?	NA	Drives?	NA	
Safety / Operational Observations						
Lights Work?	Yes - All	Wipers Work?	NA	Gauges Work?	NA	City Horn Works?
Air Horn Works?	NA					
Additional Observation Detail						

Wear and Tear Items	
FRONT	RIGHT CORNER POSTED DENTED AT BOTTOM, SMALL DINGS AT LEFT POST
LEFT SIDE	SCRATCHES / LINEAR DENTS, PEELED AREA AND WALL PANEL PATCH
REAR	PAINT STARTING TO FLAKE BELOW DOOR
INTERIOR	2 SECTIONS OF LINER MISSING AT RIGHT WALL
TIRES	2 MEASURE BELOW 10/32

Condition report only. National Inspection Services does not guarantee mechanical reliability.