



National Inspection Services
: 179217 on 01/17/2020
VIN: 1S12E9533DE526806 Unit: 13114

InPlaceAuction LLC. Ed Castagna
68 S Service Rd Melville, NY 11747 USA
(516) 297-7775

2013 STRICK DRY VAN TRAILER

DRY VAN TRAILER Specifications	
Axles	Tandem 20,000 Front / 20,000 Rear
Spread Axle	No
Suspension	Air Ride
Tire Size F	295/75R22.5
Tire Size R	295/75R22.5
Wheels	Steel
Rear Door	Swing
Interior Height	110"
Exterior	162"H 102"W 53'L
Exterior Color	WHITE

Drive Options

Inspection Photos



Notes / Description

HUB READING = 86992



National Inspection Services
: 179217 on 01/17/2020
VIN: 1S12E9533DE526806 Unit: 13114

InPlaceAuction LLC. Ed Castagna
68 S Service Rd Melville, NY 11747 USA
(516) 297-7775

2013 STRICK DRY VAN TRAILER PHOTOS





National Inspection Services
 # : 179217 on 01/17/2020
 VIN: 1S12E9533DE526806 Unit: 13114

InPlaceAuction LLC. Ed Castagna
 68 S Service Rd Melville, NY 11747 USA
 (516) 297-7775

2013 STRICK DRY VAN TRAILER

Brakes	
17	17
18	18
Additional Brake Detail	

Tires			
Front 295/75R22.5	/ 32	/ 32	Rear 295/75R22.5
Goodyear 12 / 32 Steel	Goodyear 10 / 32 Steel	Goodyear 11 / 32 Steel	Goodyear 3 / 32 Steel
Continental 6 / 32 Steel	Firestone 6 / 32 Steel	General 11 / 32 Steel	General 10 / 32 Steel
Additional Tire Detail			

General Observations						
Oil Milky?	Oil Leaks?	NA	Water Leaks?	NA	Oil in Coolant?	NA
Clutch Play?	NA	Starts?	NA	Drives?	NA	
Safety / Operational Observations						
Lights Work?	Yes - All	Wipers Work?	NA	Gauges Work?	NA	City Horn Works?
Air Horn Works?	NA					
Additional Observation Detail						

Wear and Tear Items	
FRONT	RIGHT CORNER POST DENTED AT BOTTOM, SMALL DINGS AND SCRATCH AT LEFT POST
REAR	PAINT STARTING TO FLAKE BELOW DOOR
RIGHT SIDE	CHIPPED / SCRATCHED
TIRES	A FEW WORN, 3 MEASURE BELOW 10/32

Condition report only. National Inspection Services does not guarantee mechanical reliability.

© 2020 National Inspection Services (NIS)
 101 W. Shrader St. Liberty, MO 64068
www.nationalinspect.com