


SPEC & INSPECTION RECORD

VENDOR		SERIAL NO.:	4V4NL9EH3BN 296447
AVAILABLE		UNIT NO.	
MILEAGE	605235	HRS.	
Color	Burgundy	Wheels Front	AD
Quantity		tire size	11R22.5
Year	2011	Wheels Rear	AD
Make	Volvo	tire size	11R22.5
Model	730		
W.B.			
Engine Make	Volvo	VERT/EX	Single
Model	D13	Custom Interior	
HP:	435		
Jake	4	Sleeper Size	77"
Trans. Speed	13	Sleeper Type	midrise w/ upper Fairings
Trans Type (D, O, A)	RTOL-16909A		
Susp.	Air	Tractor Pkg.	
Brakes	(good)	Fuel Tanks	Dual 125's
Frt. Axle	12500	Aero Pkg.	Full Chassis Fairings
Rear Axle	A0000		
Config.	6x4		
Ratio	3.42	Sliding 5th Whl.	12" Slider
P/S	4	NOTE!	
A/C			
GLASS	Chips		
TIRE% OR 32NDS			
TIRES			
FA		Needed To Meet Terms/ Conditions:	
RA		Hood Mirrors	
RA		D/S Lower Cabinet Doors	
	25% - 30% All Around	Dat Repairs \$2753.35	
		Body Equipment	
		P Windows	
		PLATE	
		H/P Mirrors	
		Work station	
		Rig Master APU	
		Load Lock BRACKETS	
		Block Heater	
		Shore Power	
PRICE			
Appraiser:			
VENDOR CONTACT		9 spd converted to 13 spd	
PHONE			
LOCATION			

* Estimated Repairs Needed *

Case Number: 7013177 - Repair Order Number: 47983 - Purchase Order Number: n/a
 Service Writer: Roadruck, Buddy - Case Date: 06/29/16 01:12 pm EDT

Inplace Auction	Unit #: 19415
Address: IN Phone: (516) 229-1968 Fax: Cust #:	Asset: 2011 Volvo VNL Serial #: BN296447 VIN: 4V4NC9EH3BN296447 Engine: D13 Engine Hours: 0 <div style="text-align: right;"> Miles: 605,235 Warranty Start: 1/7/2011 In Service: 5 Years 6 Months </div> <div style="text-align: right;">  BN296447 </div>

ID	Description	Labor	Parts	Core Charge	Total
1	inspection and general check over of truck and advise	\$248.00	\$0.00	\$0.00	\$248.00
2	rpl. p.s. reservoir Parts: (1) HYDRAULIC FLUID TANK 6455, (3) atf Complaint: p.s. leak Cause: res. cracked Correction: r&r res. as needed	\$248.00	\$157.20	\$0.00	\$405.20
3	5th wheel Parts: (1) KIT 9229	\$310.00	\$77.99	\$0.00	\$387.99
4	wiper motor Parts: (1) WIPER MOTOR 3631	\$186.00	\$81.36	\$0.00	\$267.36
5	windshield Parts: (1) WINDSHIELD 8431	\$223.20	\$142.18	\$0.00	\$365.38
6	Batt. Parts: (2) LOCK ROD 3131, (4) Batt.	\$186.00	\$333.38	\$0.00	\$519.38
7	lights Parts: (3) CLR/MKR, M1 LITE KIT YEL Complaint: repair inop. lights Cause: 3 bad side lights and bad rear light wiring. Correction:	\$310.00	\$91.05	\$0.00	\$401.05

(Volvo) - Fleet: Inplace Auction - Unit: 19415 -- Asset: 2011 Volvo VNL -- S/N: BN296447

replace 3 inop. side marker lights and remove inop. aftermarket lights on flap hangers.				
---	--	--	--	--

Parts: \$883.16
Labor: \$1,711.20
Core: \$0.00
Haz. Waste: \$0.00
Shop: \$100.00
Freight: \$0.00
Tax: \$58.99

TOTAL: \$2,753.35

This estimate is subject to teardown and inspection and is valid for 30 days from date above. I, the undersigned, authorize you to perform the repairs and furnish the necessary materials. I understand any costs verbally quoted are an estimate only and not binding. Your employees may operate vehicle for inspecting, testing and delivery at my risk. You will not be responsible for loss or damage to vehicle or articles left in it. AUTHORIZED BY: _____ DATE: ___/___/___