




### Bus Inspection Sheet

Year	Chassis	Conversion	Last 8 VIN #	# Pass	Mileage
2013	E450		DDA59588	14	46077

#### Circle or Underline

Starts: Yes / No  
 Batteries: Good / OK / Bad  
 Engine: Gas / Diesel / Other  
 Runs / Knocks / Smokes / Leaks  
 Trans: Shift / Slips / Leaks  
 Front A/C: Yes / No - Cold / Cool / Warm  
 Back A/C: Yes / No - Cold / Cool / Warm  
 Heater: Yes / No - Hot / Warm / Cold  
 Lights: Hdts: Yes / No Tails: Yes / No  
 Lfblk: Yes / No Lrbk: Yes / No  
 Rrbk: Yes / No Rrblk: Yes / No  
 BrakeLgt: Yes / No  
 Running Lights: Yes / No  
 Int Lghts: Yes / No  
 Prk Lghts: Yes / No

#### Mark All Body Damage Locations On The Below:



Wipers: Yes / No  
 Washer: Yes / No

W/C Lift Works: Yes / No / N/A

Windshield: Good / Chipped / Cracked  
 LS Windows: Good / Fair / Bad  
 RS Windows: Good / Fair / Bad  
 Rear Window: Good / Fair / Bad

Entrance Door Opens: Yes / No  
 Door Condition: Good / Fair / Bad

Drivers Seat: Good / Fair / Bad  
 Pax Seats: Good \_\_\_ Fair \_\_\_ Bad \_\_\_

Floor: Good / Fair / Bad

#### Tires:

Front LT: Good / Fair / Bad  
 Front RT: Good / Fair / Bad  
 Back ILT: Good / Fair / Bad  
 Back IRT: Good / Fair / Bad  
 Back OLT: Good / Fair / Bad  
 Back ORT: Good / Fair / Bad

Front Bumper: Good / Fair / Bad  
 Rear Bumper: Good / Fair / Bad

Wheel Covers: Front Left: Good / Fair / Bad  
 Front Right: Good / Fair / Bad  
 L Rear: Good / Fair / Bad  
 R Rear: Good / Fair / Bad

#### Additional Comments

Paint Chipped SIDE VIEW WINDOW

---



---



---



---



---