



National Inspection Services  
# : 179215 on 01/17/2020  
VIN: 1S12E9534DE526765 Unit: 13115

InPlaceAuction LLC. Ed Castagna  
68 S Service Rd Melville, NY 11747 USA  
(516) 297-7775

## 2013 STRICK DRY VAN TRAILER

DRY VAN TRAILER Specifications	
Axles	Tandem 20,000 Front / 20,000 Rear
Spread Axle	No
Suspension	Air Ride
Tire Size F	295/75R22.5
Tire Size R	295/75R22.5
Wheels	Steel
Rear Door	Swing
Interior Height	110"
Exterior	162"H 102"W 53'L
Exterior Color	WHITE

Drive Options

### Inspection Photos



Notes / Description
HUB READING = 181983



National Inspection Services  
# : 179215 on 01/17/2020  
VIN: 1S12E9534DE526765 Unit: 13115

InPlaceAuction LLC. Ed Castagna  
68 S Service Rd Melville, NY 11747 USA  
(516) 297-7775

## 2013 STRICK DRY VAN TRAILER PHOTOS





National Inspection Services  
 # : 179215 on 01/17/2020  
 VIN: 1S12E9534DE526765 Unit: 13115

InPlaceAuction LLC. Ed Castagna  
 68 S Service Rd Melville, NY 11747 USA  
 (516) 297-7775

## 2013 STRICK DRY VAN TRAILER

Brakes	
13	13
11	11
Additional Brake Detail	

Tires			
Front 295/75R22.5	/ 32	/ 32	Rear 295/75R22.5
Bridgestone 8 / 32 Steel	Bridgestone 7 / 32 Steel	Michelin 9 / 32 Steel	Michelin 9 / 32 Steel
9 / 32 Steel	14 / 32 Steel	Goodyear 3 / 32 Steel	Goodyear 5 / 32 Steel
Additional Tire Detail			
UNLISTED TIRES = ROADMASTER			

General Observations						
Oil Milky?	Oil Leaks?	NA	Water Leaks?	NA	Oil in Coolant?	NA
Clutch Play?	NA	Starts?	NA	Drives?	NA	
Safety / Operational Observations						
Lights Work?	Yes - All	Wipers Work?	NA	Gauges Work?	NA	City Horn Works?
Air Horn Works?	NA					
Additional Observation Detail						

Wear and Tear Items	
TRACTOR HOOKUPS	BROKEN BLUE LINE COUPLER AND MISSING ELECTRICAL COVER - BRAKES LOCKED
FRONT	SMALL DENTS AT LOWER LEFT CORNER
BUMPER	SLIGHTLY BENT UPWARD AT RIGHT SIDE
REAR	PAINT STARTING TO FLAKE BELOW DOOR
TIRES	WORN, 7 MEASURE BELOW 10/32

Condition report only. National Inspection Services does not guarantee mechanical reliability.