



National Inspection Services  
# : 179211 on 01/17/2020  
VIN: 1S12E9539DE526762 Unit: 13123

InPlaceAuction LLC. Ed Castagna  
68 S Service Rd Melville, NY 11747 USA  
(516) 297-7775

## 2013 STRICK DRY VAN TRAILER

### DRY VAN TRAILER Specifications

Axles	Tandem 20,000 Front / 20,000 Rear
Spread Axle	No
Suspension	Air Ride
Tire Size F	295/75R22.5
Tire Size R	295/75R22.5
Wheels	Steel
Rear Door	Swing
Interior Height	110"
Exterior	162"H 102"W 53'L
Exterior Color	WHITE

Drive Options
---------------

### Inspection Photos



### Notes / Description

HUB READING=090685,



National Inspection Services  
# : 179211 on 01/17/2020  
VIN: 1S12E9539DE526762 Unit: 13123

InPlaceAuction LLC. Ed Castagna  
68 S Service Rd Melville, NY 11747 USA  
(516) 297-7775

## 2013 STRICK DRY VAN TRAILER PHOTOS





National Inspection Services  
 # : 179211 on 01/17/2020  
 VIN: 1S12E9539DE526762 Unit: 13123

InPlaceAuction LLC. Ed Castagna  
 68 S Service Rd Melville, NY 11747 USA  
 (516) 297-7775

## 2013 STRICK DRY VAN TRAILER

Brakes	
10	10
11	11
Additional Brake Detail	

Tires			
Front 295/75R22.5	/ 32	/ 32	Rear 295/75R22.5
Firestone 6 / 32 Steel	Firestone 6 / 32 Steel	General 10 / 32 Steel	10 / 32 Steel
Bridgestone 11 / 32 Steel	Bridgestone 4 / 32 Steel	Bridgestone 6 / 32 Steel	Goodyear 6 / 32 Steel
Additional Tire Detail			
TIRE BRAND=DAYTON			

General Observations						
Oil Milky?	Oil Leaks?	NA	Water Leaks?	NA	Oil in Coolant?	NA
Clutch Play?	NA	Starts?	NA	Drives?	NA	
Safety / Operational Observations						
Lights Work?	Yes - All	Wipers Work?	NA	Gauges Work?	NA	City Horn Works?
Air Horn Works?	NA					
Additional Observation Detail						

Wear and Tear Items	
FRONT	LEFT CORNER DENTED AND SCRATCHED
REAR	PAINT STARTING TO FLAKE BELOW DOOR
TIRES	SEVERAL WORN, 5 MEASURE BELOW 10/32

Condition report only. National Inspection Services does not guarantee mechanical reliability.

© 2020 National Inspection Services (NIS)  
 101 W. Shrader St. Liberty, MO 64068  
[www.nationalinspect.com](http://www.nationalinspect.com)